

**Souneeds** Company – Get Expert Services at Your Door Step

## **Air Condition Rate Card**

*Visitation Fee Charges Applied At 299 per Service  
&*

*Conveyance Charges are Applied At ₹ 199 per Appliance*

*All prices below include the cost of spare parts, sourcing, and partner conveyance. Please pay only ₹199 for conveyance; no extra amount is required.*

## **Electrical Parts Rate Card**

<b>Description</b>	<b>Service Charges ₹</b>
<i>Non-Inverter PCB Repaired</i>	<i>1199 + Conveyance + Visitation Fee</i>
<i>Inverter PCB</i>	<i>3999 + Conveyance + Visitation Fee</i>
<i>Replace LVT Low Voltage Thermostat Ac/Dc</i>	<i>7991199 + Conveyance + Visitation Fee</i>
<i>Replace Sensor Inverter/Non-Inverter</i>	<i>350/550 + Conveyance + Visitation Fee</i>
<i>Contactors Replaced (Signal Poll)</i>	<i>699 + Conveyance + Visitation Fee</i>
<i>Contactors Replaced Daikin/O-General</i>	<i>1299 + Conveyance + Visitation Fee</i>
<i>Convert Normal To Pcb With Handset</i>	<i>1499 + Conveyance + Visitation Fee</i>
<i>Fan Capacitor 1.0 To 6 Mfd</i>	<i>199 + Conveyance + Visitation Fee</i>
<i>Fan Capacitor 8 To 10</i>	<i>299 + Conveyance + Visitation Fee</i>
<i>Compressor Capacitor 25 To 60</i>	<i>599 + Conveyance + Visitation Fee</i>
<i>Compressor &amp; Fan Motor Capacitor Combo</i>	<i>699 + Conveyance + Visitation Fee</i>

<i>Inverter Ac Pcb Refurbish/ New</i>	<i>7599/9599 + Conveyance + Visitation Fee</i>
---------------------------------------	--

### **Gas Charging Rate Card**

<b>Description</b>	<b>Service Charges ₹</b>
<i>Gas Charging R –22</i>	<i>1950 + Visitation Fee</i>
<i>Gas Charging R – 32 &amp; R 410 A</i>	<i>2250 + Visitation Fee</i>
<i>Leak Testing + Vacuum + Blazing</i>	<i>799</i>

### **Rate Card**

<i>Copper coil condenser 1.5-ton split (Outdoor)</i>	<i>4599 + Conveyance + Visitation Fee</i>
<i>Copper coil condenser 2-ton split (Outdoor)</i>	<i>5599 + Conveyance + Visitation Fee</i>
<i>Copper cooling coil 1.0-ton split (Outdoor)</i>	<i>3599 + Conveyance + Visitation Fee</i>
<i>Capillary and filter replaced</i>	<i>399</i>
<i>Compressor 0.8 - 1 ton</i>	<i>7599 + Conveyance + Visitation Fee</i>
<i>Compressor 1.5 ton</i>	<i>8599 + Conveyance + Visitation Fee</i>
<i>Compressor 2 ton</i>	<i>9799 + Conveyance + Visitation Fee</i>
<i>Expansion valve replaced</i>	<i>1399 + Conveyance + Visitation Fee</i>
<i>Copper cooling coil/condenser coil (window AC)</i>	<i>4599/6599 + Conveyance + Visitation Fee</i>
<i>Replacement compressor (1 ton) R-22 / (R-32/410)</i>	<i>3899/4899 + Conveyance + Visitation Fee</i>

<i>Replacement compressor (1.5 ton) R-22 / (R-32/410)</i>	<i>4899/5899 + Conveyance + Visitation Fee</i>
<i>Replacement compressor (2 ton) R -22 / (R-32/410)</i>	<i>5999/7299 + Conveyance + Visitation Fee</i>
<i>Service valve replaced - ¼</i>	<i>399 + Conveyance + Visitation Fee</i>
<i>Service valve replaced - ½</i>	<i>499 + Conveyance + Visitation Fee</i>
<i>Service valve replaced - 5/8</i>	<i>599 + Conveyance + Visitation Fee</i>
<i>Copper cooling coil (split AC) - 1 ton (Indoor Unit) R 22 / R32 / R 410</i>	<i>5299 + Conveyance + Visitation Fee</i>
<i>Copper cooling coil (split AC) 1.5-ton (Indoor Unit) R 22 / R 32 / R 410</i>	<i>6299 + Conveyance + Visitation Fee</i>
<i>Copper cooling coil (split AC) - 2 ton (Indoor Unit) R 22 / R32 / R 410</i>	<i>7299 + Conveyance + Visitation Fee</i>
<i>Copper cooling coil (split AC) O general &amp; Mitsubishi - 1.5 ton (indoor unit) R 22 / R 32 / 410</i>	<i>7800 + Conveyance + Visitation Fee</i>

### **Rate Card**

<i>Copper cooling coil / condenser coil (window AC) -2 ton</i>	<i>5299/6599 + Conveyance + Visitation Fee</i>
<i>Fuse Change In PCB</i>	<i>199 + Visitation Fee</i>
<i>Cooling coil Repair with Anti Rust Coating</i>	<i>899 + Conveyance + Visitation Fee</i>
<i>Anti Rust Coating for All Type of Ac</i>	<i>799 + Conveyance</i>

### **Fan Motor Rate Card**

<i>Fan motor – split AC (Out Door) Ac / Dc</i>	<i>1499 / 2499 + Conveyance + Visitation Fee</i>
<i>Blower motor – split AC Indoor Ac / Dc</i>	<i>2199 / 3499 + Conveyance + Visitation Fee</i>
<i>Blower replaced Window / Indoor Unit</i>	<i>1199 / 1699 + Conveyance + Visitation Fee</i>
<i>Replace flap/swing moto</i>	<i>299 + Conveyance + Visitation Fee</i>
<i>Motor bearing change</i>	<i>899 + Conveyance + Visitation Fee</i>
<i>Fan motor – window AC</i>	<i>2499 + Conveyance + Visitation Fee</i>
<i>Noise issue repair</i>	<i>1+ Visitation Fee</i>

### ***Installation Rate Card***

<b><i>Description</i></b>	<b><i>Service charge ₹</i></b>
<i>1 meter copper pipe set China (with insulation, wire light)</i>	<i>899 (Conveyance on Bulk)</i>
<i>1 meter copper pipe set India (with insulation, wire Medium)</i>	<i>1099 (Conveyance on Bulk)</i>
<i>1 meter copper pipe set Malaysia (with insulation, wire Heavy)</i>	<i>1199 (Conveyance on Bulk)</i>
<i>1 meter copper pipe set Heavy (with insulation, wire Heavy)</i>	<i>1299 (Conveyance on Bulk)</i>
<i>Indoor unit reinstalled</i>	<i>699 + Visitation Fee</i>
<i>Fastener complete set</i>	<i>199</i>
<i>Floor stand</i>	<i>699 + Conveyance</i>
<i>Universal back plate</i>	<i>299 + Conveyance</i>
<i>Foam-jet AC service</i>	<i>499</i>
<i>AC installation Window Without Wood</i>	<i>499</i>
<i>AC uninstallation Window</i>	<i>299</i>

<i>Anti – rust spray (avoid gas leak)</i>	<i>899 Conveyance</i>
<i>Lite AC service</i>	<i>399</i>
<i>AC uninstallation Spilt Type</i>	<i>699</i>
<i>Ac Installation Spilt Type</i>	<i>1499</i>

### ***Rate Card***

<i>Description</i>	<i>Service charge ₹</i>
<i>Water leakage repaired – split AC</i>	<i>99 + Visitation Fee</i>
<i>Adjust grill locks</i>	<i>1+ Visitation Fee</i>
<i>Adjust pipe and tight compressor screw</i>	<i>1+ Visitation Fee</i>
<i>Connector wires replaced (1m)</i>	<i>99 + Visitation Fee</i>
<i>Tighten/ replace thimble</i>	<i>99 + Visitation Fee</i>

### ***Rate Card***

<i>Drain pipe adjust</i>	<i>1 + Visitation Fee</i>
<i>Noise adjustment in motor</i>	<i>1 + Visitation Fee</i>
<i>Noise adjustment in blower</i>	<i>1 + Visitation Fee</i>
<i>Noise adjustment in cabinet</i>	<i>1 + Visitation Fee</i>
<i>Noise adjustment in swing flap</i>	<i>1 + Visitation Fee</i>
<i>Water leakage repaired- window AC</i>	<i>1 + Visitation Fee</i>

### ***Rate Card***

<i>Description</i>	<i>Service charge ₹</i>
<i>AC fan blade Window / Spilt Outdoor</i>	<i>699 / 799 + Conveyance + Visitation Fee</i>
<i>Grill cover (Window)</i>	<i>1599 + Conveyance + Visitation Fee</i>
<i>Swing blade replaced</i>	<i>399 + Conveyance + Visitation Fee</i>
<i>Universal remote</i>	<i>499 + Conveyance + Visitation Fee</i>
<i>Water tray</i>	<i>499 + Conveyance + Visitation Fe</i>

### ***Rate Card***

<i>Drain pipe adjust</i>	<i>99 + Visitation Fee</i>
<i>Insulation refixes</i>	<i>99 + Visitation Fee</i>
<i>Noise issue repair</i>	<i>1 + Visitation Fee</i>
<i>Stabilizer connection</i>	<i>1 + Visitation Fee</i>

### ***New Indoor & Outdoor Rate Card***

<i>Description</i>	<i>Service charge ₹ (Actual price at time of installation)</i>
<i>Jobu (Diken) Indoor 1.5 ton</i>	<i>14299 + Conveyance</i>
<i>Raque (Hitachi) Indoor 1.5 ton</i>	<i>11599 + Conveyance</i>
<i>Godrej Indoor 1.5 ton</i>	<i>11299 + Conveyance</i>

<i>Jobu (Diken) Indoor 1.8 ton</i>	<i>17599 + Conveyance</i>
<i>Raque (Hitachi) Indoor 2.0 ton</i>	<i>14599 + Conveyance</i>
<i>Godrej Indoor 2.0 ton</i>	<i>14299 + Conveyance</i>
<i>Sakoda Outdoor 1.5 ton (without Compressor &amp; Accessories)</i>	<i>8599 + Conveyance</i>
<i>Sakoda Outdoor 2.0 ton (without Compressor &amp; Accessories)</i>	<i>11599 + Conveyance</i>
<i>Speed Outdoor 1.5 ton (without Compressor &amp; Accessories)</i>	<i>10299 + Conveyance</i>
<i>Speed Outdoor 2.0 ton (without Compressor &amp; Accessories)</i>	<i>13599 + Conveyance</i>

### **Labour Charges Only – Material Not Included**

<b>Description</b>	<b>Service charge ₹</b>
<i>Stabilizer Fitting</i>	<i>299</i>
<i>Power Problem</i>	<i>299</i>
<i>Capacitor Installation / uninstallation</i>	<i>399</i>
<i>Pcb Installation / uninstallation</i>	<i>399</i>
<i>Fan Motor uninstallation</i>	<i>499</i>

<i>Fan Motor installation</i>	799
<i>Fan &amp; Blower Uninstallation</i>	399
<i>Fan &amp; Blower Installation</i>	699
<i>Cooling &amp; Condenser Coil Uninstallation</i>	599
<i>Cooling &amp; Condenser Coil Installation</i>	599
<i>Leak Testing + Blazing</i>	399
<i>Gas Charging</i>	799
<i>Compressor uninstallation</i>	499
<i>Compressor Installation &amp; Gas Charging</i>	1199

### ***Air Condition Cooper Piping***

<b><i>Description</i></b>	<b><i>Service charge ₹ Rate/Mtr.</i></b>
<i>China Cooper + Insulation Foam + Venial Tape + Light Wire (Company) + Drain Pipe 20 mm + Zeri + Clamping + Visitation Fee+ Cattage</i>	850 (Conveyance on Bulk order)
<i>China Cooper + Insulation Foam + Venial Tape + Medium Wire (Company) + Drain Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage</i>	875 (Conveyance on Bulk order)
<i>China Cooper + Insulation Foam + Venial Tape + Heavy Wire (Company) + Drain</i>	899 (Conveyance on Bulk order)



<i>Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage</i>	
<i>Indian Cooper + Insulation Foam + Venial Tape + Light Wire (Company) + Drain Pipe 20 mm + Zeri + Clamping + Visitation Fee+ Cattage</i>	<i>870 (Conveyance on Bulk order)</i>
<i>Indian Cooper + Insulation Foam + Venial Tape + Medium Wire (Company) + Drain Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage</i>	<i>899 (Conveyance on Bulk order)</i>
<i>Indian Cooper + Insulation Foam + Venial Tape + Heavy Wire (Company) + Drain Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage</i>	<i>985 (Conveyance on Bulk order)</i>
<i>Malaysia Cooper + Insulation Foam + Venial Tape + Light Wire (Company) + Drain Pipe 20 mm + Zeri + Clamping + Visitation Fee+ Cattage</i>	<i>925 (Conveyance on Bulk order)</i>
<i>Malaysia Cooper + Insulation Foam + Venial Tape + Medium Wire (Company) + Drain Pipe 25 mm + Clamping + Visitation Fee+ Cattage</i>	<i>975 (Conveyance on Bulk order)</i>
<i>Malaysia Cooper + Insulation Foam + Venial Tape + Heavy Wire (Company) + Drain Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage</i>	<i>999 (Conveyance on Bulk order)</i>
<i>Mandav Cooper + Insulation Foam + Venial Tape + Medium Wire (Company) + Drain Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage</i>	<i>1099 (Conveyance on Bulk order)</i>
<i>Mandav Cooper + Insulation Foam + Venial Tape + Heavy Wire (Company) + Drain Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage</i>	<i>1199 (Conveyance on Bulk order)</i>
<i>Mandav (Heavy) Cooper + Insulation Foam + Venial Tape + Heavy Wire (Company) + Drain Pipe 25 mm + Zeri + Clamping + Visitation Fee+ Cattage</i>	<i>1299 (Conveyance on Bulk order)</i>
<i>Without Any Material or Zeri Only Labour Charges</i>	<i>240/mtr.</i>
<i>Site Inspection Charges for Piping</i>	<i>399</i>

## **Amc Charges**

<b>Description</b>	<b>Service charge ₹ Rate / Unit</b>
<i>Non-Comprehensive Including All Electric Parts, Gas Charging, Fan Motor, Pcb Repairing, Servicing For 1.0- &amp; 1.5-Ton Ac (Non-Inverter)</i>	<i>3499 (Excluding GST)</i>
<i>Comprehensive Including All Electric Parts, Gas Charging, Fan Motor Repairing, Pcb Repairing, Compressor Replacement, Servicing For 2.0 – Ton Ac (Non-Inverter)</i>	<i>7499 (Excluding GST)</i>
<i>Non-Comprehensive Including All Electric Parts, Gas Charging, Fan Motor Repairing, Pcb Repairing, Servicing For 2.0 – Ton Ac (Non-Inverter)</i>	<i>5499 (Excluding GST)</i>
<i>Non-Comprehensive Including All Electric Parts, Gas Charging, Fan Motor, Pcb Repairing, Servicing For 1.0 &amp; 1.5 – Ton Ac (Inverter)</i>	<i>7499 (Excluding GST)</i>
<i>Non-Comprehensive Including All Electric Parts, Gas Charging, Fan Motor, Pcb Repairing, Servicing For 2.0 – Ton Ac (Inverter)</i>	<i>8499 (Excluding GST)</i>
<i>Non-Comprehensive Including All Capacitors, Servicing, &amp; Minor Repairing Work &amp; Visitation Fee For 1.0, 1.5 &amp; 2.0– Ton Ac (Non-Inverter)</i>	<i>1899 (Excluding GST)</i>
<i>Non-Comprehensive Including Visitation Fee, Servicing &amp; Minor Repairing Work For 1.0, 1.5 &amp; 2.0 – Ton Ac (Inverter)</i>	<i>1899 (Excluding GST)</i>

## **AMC Terms & Conditions**

Damage, rust, breakage caused by electrical faults, plastic items, or any other method is not covered under AMC.

Only 2 times gas charging and leakage testing (near drain/nala or industrial areas) are included in AMC.

Only repair work will be performed under AMC. If any part is not repairable and requires new or replacement parts, or if replacement is requested by the customer, it will be chargeable.

New & Replacement of inverter compressor or PCB is not covered under AMC; charges will apply as per current market price.

Only 2 Servicing are free in AMC;

## **Note**

### **Service Terms & Conditions**

*The amount paid at the time of booking is a **visitation fee**, which will be **adjusted in the final installation quote**.*

*If **spare parts** are required, the technician will **procure them from the local market**, and **cartage charges** will be **applicable**.*

***Warranty duration** will be mentioned on the **bill or service receipt** by the **company or technician** after the work is completed.*

*There are **no hidden charges**.*

## **Please Note**



*If spare parts are needed, the Technician will source them from the local market*



## **Our Installation process**

### **Inspection**

*We will check the space where you want to install the Appliances*

### **2. Installation**

*We will install the appliances with care*

### **3. Cleanup**

*We will clean the area once work is done*



REPAIR SERVICE

## **Our Repairing & Services Process**

### **1. Inspection & quote**

*We inspect the appliance & share a repair quote for approved*

### **2. Approval or expert review**

*Repair begins after your approval, if you are unsure, you can call our expert*

### 3. Service, Repair & spare parts

*If necessary, we will provide spare parts at fixed rates during the repair & service.*

### 4. Warranty activation

*Your appliance will automatically come under warranty Period after the repair Given by Technician/Company on time of billing*



#### **Souneed\_Promise**



*Up to 10 to 365 days warranty on different product & services*



*Fixed Rate Card*



*On Call Repair Quote Verification*



*Up to 3000 Damage Cover*



*Surprise Checking/Feedback at the time or after the work by **Senior technicians***

### **Our Top Technicians**



*Background Verified by **Souneeds***



*Trained across all major brands by  
**Souneeds Experianesd Techinitions***

## **What we'll need from you**

*Buckets*

*Point*

*Ladder / Stool*

*Clean Cloth*

## **What We Will Do and Not Do on the Work Site**

### **For The Service Of Unit**

*Applicable For Both Spilt & Window Acs*

*Camical / Foam & Jet Cleaning of Indoor With Gaket*

*Jet Spray Cleaning of Outdoor only*

## ***For Leakage Unit***

*Additional Charges Apply For More Than 2 Leaks  
Cooling Coil Repair Includes Anti Rust Coating  
To Extend The Ac Life.  
We Don't Repair Centralized Acs & Vrv System On  
Domestic Compland*

## ***For Installation Not Included***

Cost of wiring will be charged extra  
Masonry / core cutting is not included

## ***What's Included***

*Installation of outdoor & indoor with piping 10 ft only  
After 10 ft charged Rs – 200/mtr extra.*